

## Garcia, Delia

---

**From:** Garcia, Delia  
**Sent:** Monday, November 24, 2014 2:10 PM  
**To:** Burnett, Michael; Gonzales, Kristina  
**Subject:** FW: 8th group of photos Black Tea Oil Drilling Sites  
**Attachments:** DSC00057.jpg; DSC00058.jpg; DSC00059.jpg; DSC00060.jpg; DSC00061.jpg

Delia Garcia, PhD  
Environmental Scientist  
WWPD/WENF  
US EPA Region 7  
11201 Renner Boulevard  
Lenexa, KS 66219  
Phone: (913) 551-7262 FAX: (913) 551-9262  
Email: Garcia.Delia@epa.gov

-----Original Message-----

From: Cory, Luke M NWK [mailto:Luke.M.Cory@usace.army.mil]  
Sent: Tuesday, September 09, 2014 12:49 PM  
To: Garcia, Delia  
Subject: 8th group of photos Black Tea Oil Drilling Sites

This is the 8th group of photos of Black Tea Oil Drilling Sites on the Smoky Hill River. This is where the pipeline crossed the Smoky Hill River and Black Tea Oil pushed fill material up over the pipeline route creating a dike across the channel. The drilling site in the background wasn't inspected, photo was taken from the opposite bank of the Smoky Hill River. It does appear that the oil drilling pad fill may extend into the channel.

Luke M. Cory  
Regulatory Team Leader  
Kanopolis Regulatory Field Office  
107 Riverside Drive  
Marquette, Kansas 67464

Direct Line: (816) 389-3027

<http://www.nwk.usace.army.mil/Missions/RegulatoryBranch.aspx>